

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOCRAPHS

HABS  
WASH  
S-LACRE.V.  
2-

Storm King Ranger Station  
Olympic National Park  
N. side of U.S. Highway 101 (near Barnes Pt.)  
Lake Crescent Vicinity  
Clallam County  
Washington

HABS No. WA-155

Eduardo Calderon, Photographer, March 1983

- WA-155-1      EXTERIOR NORTH FRONT AND WEST SIDE
- WA-155-2      EXTERIOR, NORTH FRONT
- WA-155-3      EXTERIOR, WEST SIDE, SHOWING CHIMNEY DAMAGE
- WA-155-4      EXTERIOR, WEST SOUTH SIDES, SHOWING PROXIMITY TO LAKE  
CRESCENT
- WA-155-5      EXTERIOR, SOUTHWEST CORNER
- WA-155-6      EAST SIDE, SHOWING ACCIDENT DAMAGE AND PROXIMITY  
TO U.S. HIGHWAY 101
- WA-155-7      EXTERIOR, NORTH FRONT AND EAST SIDE
- WA-155-8      EXTERIOR, NORTHEAST CORNER, SHOWING NOTCHING, DEEP PORCH  
EAVE AND LAKE CRESCENT
- WA-155-9      EXTERIOR, PARTIAL VIEW OF EAST SIDE, SHOWING PROFILE OF  
FRONT PORCH
- WA-155-10     EXTERIOR, NORTH FRONT, DETAIL OF NORTH WALL AND WINDOWS
- WA-155-11     EXTERIOR, DETAIL OF NORTH DOORWAY
- WA-155-12     EXTERIOR, NORTHWEST CORNER, NOTCH DETAIL
- WA-155-13     INTERIOR, FIRST FLOOR, NORTHWEST ROOM, SHOWING FIREPLACE AND  
STAIRWAY
- WA-155-14     INTERIOR, FIRST FLOOR, NORTHWEST ROOM, WEST WALL WITH  
FIREPLACE
- WA-155-15     INTERIOR, FIRST FLOOR, NORTHWEST ROOM, SHOWING NORTH WALL  
WITH DOORWAY AND EAST WALL WITH UPPER STAIRWAY
- WA-155-16     INTERIOR, FIRST FLOOR, NORTHWEST ROOM, FULL VIEW OF STAIRWAY
- WA-155-17     INTERIOR, SECOND FLOOR, NORTHEAST ROOM WITH DORMER